

Fig. 1




Fig. 2




Fig. 3





Fig. 4

420



680

Angle	Cosine	Sine
-2/128	0.995185	-0.146730
-1/128	0.998795	-0.049068
0	1.0	0.0
1/128	0.998795	0.049068
2/128	0.995185	0.098017
3/128	0.989177	0.146730
...	...	...
...	...	...
...	...	...
14/128	0.707107	0.634393
15/128	0.773011	0.671559
1/8	0.707107	0.707107
17/128	0.671559	0.740950
18/128	0.634393	0.773011

690

Fig. 5

692

Angle	Cosine
$x_n$	$y_n$
-2/128	0.995185
-1/128	0.998795
0	1.0
1/128	0.998795
2/128	0.995185
3/128	0.989177
...	...
...	...
...	...
14/128	0.773011
15/128	0.740951
1/8	0.707107
17/128	0.671559
18/128	0.634393

$\delta_0$   
 $\delta_1$   
 $\delta_2$   
 $\delta_3$

Fig. 6

694

Angle	Sine
$x_n$	$y_n$
-2/128	-0.146730
-1/128	-0.049068
0	0.0
1/128	0.049068
2/128	0.098017
3/128	0.146730
...	...
...	...
...	...
14/128	0.634393
15/128	0.671559
1/8	0.707107
17/128	0.740951
18/128	0.773011

$\delta'_0$   
 $\delta'_1$   
 $\delta'_2$   
 $\delta'_3$

Fig. 7




Fig. 8




Fig. 9